



Plates

- 17 standing water on the road destabilises the road
- 18 streams crossing over the road scour the road
- 19 erosion from river bank collapse resulting in flow down the side of the road causing further longitudinal erosion
- 20 erosion from uncontrolled stream flow across the road
- 21 collapsed river side bank and failure of support structure
- 22 heavily eroded banks alongside the road
- 23 eroded cut-away banks
- 24 collapsed bank alongside the road
- 25 eroded section of the road due to erosion and vehicle use
- 26 significant erosion and collapse of outer banks of switchbacks
- 27 erosion at the switchbacks due to ice cracking